

Appendix C Fluvial Geomorphic Assessment



September 15, 2022

Version 2.0
Matrix 24316-531

Sam Neale
MORRISON HERSHFIELD LIMITED
Suite 300, 125 Commerce Valley Dr. W
Markham, ON L3T 7W4


Subject: Lavender Creek Fluvial Geomorphology Assessment

Dear Sam Neale:



Two watercourses are located within the Rockcliffe Riverine Flood Mitigation Environmental Assessment study area: Black Creek and Lavender Creek. Both are within the Humber River watershed. The majority of channel within the scoped study area consists of engineered concrete channels, with the exception of Lavender Creek downstream of Symes Road. An existing conditions geomorphological assessment of Lavender Creek has been completed to identify channel characteristics, in order to evaluate future potential design alternatives that will aid in flood mitigation at Lavender Creek.

Lavender Creek originates west of Weston Road and extends approximately 1,200 m before discharging into Black Creek, draining an area of 5.79 km². Currently, Lavender Creek exhibits a very straight planform, flowing east to west from Weston Road to Symes Road in a concrete channel. The channel makes a sharp 90-degree bend at the Symes Road crossing, flowing north-westerly to Black Creek. The 400 m reach of Lavender Creek, downstream of Symes Road to the confluence at Black Creek, is currently the only alluvial channel in the study area not engineered with concrete; although, it is still highly modified and confined within a narrow riparian corridor. As it is not fully a natural channel, this section will be referred to as the alluvial reach of Lavender Creek.

A geomorphic field investigation was undertaken for the alluvial reach of Lavender Creek on December 3, 2020, to characterize channel parameters, substrate, and document indicators of instream erosion (Figure 1). Field work was limited to the segment of channel downstream of Symes Road, where the watercourse is not lined with concrete but consists of native alluvial materials, variable fill, and localized rock and concrete debris. The following geomorphic assessment includes a) a rapid field assessment (Rapid Geomorphic Assessment [RGA]/Rapid Stream Assessment Technique [RSAT]), and b) bankfull hydraulics and instream erosion threshold analyses. Lavender Creek upstream of Symes Road was not assessed as it is engineered with concrete-lined bed and banks.




- Scoped EA Study Area
- Geomorphic Cross-section Location
- TRCA Regulatory Floodline
- Watercourse
- Road
- Flow Direction



1:4,000

Datum: NAD 1983 UTM Zone 17N
North American 1983

Source: Toronto and Region Conservation Authority
City of Toronto



Matrix Solutions Inc.
ENVIRONMENT & ENGINEERING

**Rockcliffe Riverine Flood Mitigation
Municipal Class Environmental Assessment**

**Geomorphic Cross-Section
Locations in Lavender Creek**

Project No.: **202179500**

Date: **June 2022**

Map location: \\MorrisonHarris\field\2021\67\figures\and\tables\report\fluvial\geomorphology\report\Map_X_Geomorphic_Cross-Section_Locations_in_Lavender_Creek.mxd
User: syme Date Saved: 2022-06-27 12:11:15 PM

1 RAPID FIELD ASSESSMENT

Rapid field assessments consisting of the RGA (MOE 2003) and RSAT (Galli 1996) were completed to document evidence of channel instability and to evaluate stream health. The RGA consists of a checklist of indicators of channel instability that are tabulated and quantified using an index that identifies channel sensitivity based on the presence or absence of aggradation, degradation, channel widening, and planform adjustment. Overall, the index produces values that indicate whether the channel is “Stable/In Regime”, “Transitional/Stressed”, or “Stressed/Adjusting”. A stable score indicates that the channel morphology is within a range of variance for streams of similar characteristics. Any evidence of instability is isolated or associated with normal river meander propagation processes. A transitional score indicates that the channel morphology is within the range of variance of streams of similar hydrographic characteristics, but the evidence of instability is more frequent. An adjusting score indicates that the channel morphology is not within the range of variance, and evidence of instability is widespread. The RSAT provides a more qualitative and broader assessment of the overall health and functions of a reach. This system integrates visual estimates of channel conditions and numerical scoring of stream parameters using six categories: channel stability, erosion and deposition, instream habitat, water quality, riparian conditions, and biological indicators.

During the rapid assessments, bankfull channel dimensions are identified. In natural, stable streams, the bankfull channel area often represents the maximum capacity of the channel before flow spills into the floodplain, and the discharge at this stage is referred to as the bankfull discharge. In the case of Lavender Creek, bankfull dimensions were determined from obvious breaks or inflections in the cross-section profile and/or changes in vegetation due to the entrenched nature of the system. The study reach is described below with all references to left or right banks when looking in the downstream direction (refer to attached site photographs).

Downstream of Symes Road, Lavender Creek contains a relatively straight planform, with minor sinuosity observed approximately 20 m upstream of the confluence with Black Creek. The channel is entrenched and contains bank heights between 1.0 to 2.5 m. Evidence of raised manholes and outfalls along the channel corridor suggests the channel has continued to incise for several decades. Bank erosion is extensive throughout the reach as evidenced by exposed tree roots and vertical, undercut, and overhanging banks. It is evident that high flow events frequently fill and overtop the channel corridor due to the presence of debris caught in tree branches as well as localized deposition of fine material in the overbank zone.

In general, Lavender Creek lacks a well-defined pool-riffle sequence. The majority of the reach consisted of riffles and transitional sections, with the occasional shallow pool. Transitional sections were generally characterized as extended shallow flow between riffles and poorly developed pool features. At riffles, channel substrate was dominated by gravel and small cobbles, with larger cobbles/boulders or previously placed riprap noted in several locations. Shallow pool and transitional areas contained a higher abundance of sand, silt, and small gravel. Localized well sorted gravel point bars and medial bars were observed along the corridor. Bank faces were generally not well vegetated, providing evidence of ongoing active erosion; however, vegetation on the top of bank predominantly consisted of shrubs and trees, several of which were falling/leaning.

This reach was assessed with a resulting RGA score of 0.38, indicating that it is in a Transitional or Stressed condition. Based on the indicators observed, the dominant geomorphic processes/modes of adjustment are widening and degradation. Indicators of channel widening that were observed include fallen/leaning

trees, the occurrence of large organic debris, exposed tree roots, fracture lines along top of bank, and basal scour noted on inside meander bends, both sides of channel through riffle, and along a length of >50% of the reach. It is evident that the creek banks are relatively unstable and are undergoing active erosion due to the high velocity/shear stress acting on the banks at frequent high flow events. An RSAT score of 19 was calculated for this reach, indicating that it contains low stream health. The limiting indicators for stream health were poor water quality, channel stability, and riparian conditions. RGA and RSAT field forms are attached.

1.1 Bankfull Hydraulics and Instream Erosion Threshold

To specifically assess the bankfull hydraulic capacity, detailed cross-sections were measured at three locations (riffles) along Lavender Creek using a measuring tape and metre stick to supplement the Toronto and Region Conservation Authority (TRCA) 2018 topographic survey data. At each cross-section, measurements of depth from the tape to the channel invert were recorded in 0.2 m increments and plotted. The channel substrate at each cross-section was also characterized (i.e., D_{50} , D_{84}) using a modified Wolman pebble count which utilizes the random selection and characterization of individual sediment particles from the channel bed (Wolman 1954). Cross-sections were measured to gain an understanding of the bankfull channel geometry and hydraulic capacity. Table 1 provides a summary of the selected parameters and calculated hydraulics.

TABLE 1 Summary of Bankfull Parameters from Measured Cross-sections

Parameter	XS-1	XS-2	XS-3	Average
Measured				
Average Bankfull Width (m)	7.55	6.43	6.95	6.98
Average Bankfull Depth (m)	0.81	0.72	0.75	0.76
Maximum Bankfull Depth (m)	1.07	1.08	1.09	1.08
Bankfull Width:Depth Ratio	9.30	8.97	9.21	9.16
Entrenchment Ratio ⁽¹⁾	1.9	3.5	3.2	2.87
Hydraulic Radius	0.75	0.67	0.62	0.68
Channel Bed Gradient (m/m) ⁽²⁾	0.0065			
Bed Substrate and Bank Materials				
D ₁₀ (mm)	8			
D ₅₀ (mm)	19			
D ₉₀ (mm)	43			
Bank Material	Sandy loam with organic horizons and root mats; local evidence of riprap, concrete debris, artificial fill, native gravel, and clay till			
Computed ⁽³⁾				
Average Bankfull Discharge (m ³ /s)	11.8	8.4	9.59	9.93
Average Bankfull Velocity (m/s)	1.89	1.76	1.79	1.81
Average Bankfull Shear Stress (N/m ²)	47.4	42.6	43.6	44.5

(1) Entrenchment ratio is flood prone width divided by bankfull width, where flood prone width is taken at 2 times the bankfull depth

(2) Channel bed gradient taken from MIKE FLOOD model of Lavender Creek

(3) Manning's n assumed to be 0.035

XS - cross-section

As an approximate valuation of baseflow, the low-flow conditions on the date of the survey (December 3, 2020) were estimated to be in the range of 10 to 50 L/s. This assessment is based on the cross-section surveys and a visual approximation of the surface velocity, with average conditions of 3.1 m for wetted width, 0.05 m for averaged flow depth, and 0.1 to 0.3 m/s for the flow velocity.

On average, bankfull dimensions were approximately 6.98 m in width and 0.76 m in depth, with an average entrenchment ratio of 2.88. From these results, the bankfull channel was interpreted to be slightly entrenched on average, with moderate entrenchment measured in the upstream section (XS-1). A channel gradient of 0.65% was obtained from MIKE FLOOD modelling software as part of the hydraulic modelling component of the current project. Using a Manning's n of 0.035, bankfull parameters such as discharge, velocity, and shear stress were calculated. The resulting values are 9.93 m³/s, 1.81 m/s, and 44.5 N/m², respectively. Three cross-sections corresponding to the approximate location of the field-measured cross-sections were exported from MIKE FLOOD software to display the various water levels at specific return periods (Figures 2 to 4). It is noted that the average bankfull discharge calculated using our field-measured cross-section (9.93 m³/s) is significantly lower than the 2-year discharge (23.3 m³/s), highlighting the urban nature of the creek's flow regime. In most cases (XS-1 and XS-2), the 10-year flow event overtops the entrenched creek valley and disperses towards the right bank. Beyond the 10-year flow event, Lavender Creek is highly influenced by backwater from Black Creek.




FIGURE 2 Cross-section 1 Showing Bankfull and MIKE FLOOD Water Levels




FIGURE 3 Cross-section 2 Showing Bankfull and MIKE FLOOD Water Levels



FIGURE 4 Cross-section 3 Showing Bankfull and MIKE FLOOD Water Levels

To assess the frequency of sediment transport processes within Lavender Creek, an erosion threshold analysis was completed to determine the hydraulic conditions, such as the critical discharge, channel depth, and average channel velocity at which bed materials of a given particle size (D_{crit}) will tend to be mobilized (Table 2). This represents the “threshold” condition at which sediment particles will start to move. A representative cross-section was selected from the field assessment to complete the erosion threshold analysis. The erosion threshold was then calculated using empirical relationships dependent on factors such as sediment size and cohesiveness. Since the median grain size (D_{50}) for Lavender Creek was within the medium gravel range (19 mm), three approaches; Komar (1987), Chow (1959), and Miller (1977) were used to derive the threshold for the reach and were averaged.

TABLE 2 Erosion Threshold Parameters for Representative Cross-section

Parameter	Komar (1987)	Chow (1959)	Miller (1977)	Average
Critical Discharge (m^3/s)	0.75	1.0	0.93	0.89
Critical Depth (m)	0.33	0.37	0.36	0.35
Critical Velocity (m/s)	0.77	0.85	0.83	0.82
Critical Shear Stress (N/m^2)	12.2	14.4	13.8	13.5
Shields Number at Channel-forming Flow	0.23			

The average critical discharge of $0.89 m^3/s$ indicates that the transport of the median sediment size is initiated at approximately 10% of the bankfull flow. This calculation confirms the rapid field assessment results that Lavender Creek is erosive in nature given that a flow one tenth of the bankfull event is capable of entraining the median sediment size. This interpretation is also evident in the observed channel bars of loose gravel within Lavender Creek.

As an additional reference, the Shields number was calculated at the channel-forming flow to classify Lavender Creek as either a transitional or threshold-type channel (Church 2006). For natural mixed-gravel bed channels, where the bankfull flow is assumed to be the channel forming flow, the average Shield’s ratio is 0.045. The Shield’s number at the channel-forming flow for Lavender Creek was calculated to be 0.23, indicating that it is a transitional-type channel and sediment transport events are more frequent than a typical bankfull, threshold-type channel.

2 FLUVIAL GEOMORPHIC ASSESSMENT CONCLUSIONS

Results of the fluvial geomorphic assessment for Lavender Creek confirm its impacted condition as an erosive urban channel, whereby local fill and native alluvial material that make up the channel boundary are relatively erodible as they are frequently subjected to flashy storm runoff responses from the upstream urban drainage network. The RGA and RSAT indices classify the channel stability as transitional to stressed and indicate a low stream health score. The dominant fluvial processes are widening and degradation, with a poorly developed riffle-pool morphology and irregular bars of transient bed load sediments. Mostly in a degraded state, local riprap and concrete debris provide minimal erosion control.

The above field observations and rapid assessment scores have been corroborated by analytical results for the bankfull hydraulics and an erosion threshold for the bed material. The calculated critical discharge for entrainment of the median grain sizes ($0.89 m^3/s$) is only 10% of the bankfull discharge capacity ($9.93 m^3/s$), and the bankfull discharge is less than half (43%) of the 2-year discharge. The channel is considered to be moderately to slightly entrenched, with entrenchment ratios that range from 1.9 to 3.5.

The hydraulic capacity of the floodway corridor tends to be greater than the 10-year flood discharge of 47.1 m³/s, which is almost 5 times greater than bankfull discharge and more than 50 times greater than the critical discharge. These results are meaningful because the bankfull, 2-year, and 10-year discharges are contained within the narrow floodway corridor and are extremely competent to mobilize and transport the prevailing gravel bed material. As such, the existing channel does not function as an equilibrium threshold channel because most of the geomorphic work of erosion and sediment transport occurs well below the bankfull discharge, with multiple and frequent sediment transport events expected to occur each year. Based on the calculated Shields ratio of 0.23 for the bankfull or channel-forming discharge, the channel morphology functions in a transitional state between threshold and labile conditions (Church 2006).

The results and interpretations presented here are not unexpected for an urban channel such as Lavender Creek, with a highly modified urban runoff regime (where $Q_2 > Q_{BF} > Q_{crit}$) and an alluvial channel dominated by fine gravel bed materials ($D_{50} = 19$ mm). The implication of this assessment on the consideration of conceptual design alternatives is that a stable and sustainable natural channel design of Lavender Creek would require creating a novel channel morphology, boundary condition, and corridor configuration commensurate with the flow frequency and hydraulics of the modified urban runoff regime. However, it is expected that the preferred solution will be engineered with a low channel roughness to address the flooding hazard, and thus application of a natural channel design approach in this case is not expected.

3 CLOSURE

We trust that this letter report suits your present requirements. If you have any questions or comments, please call either of the undersigned at 905.877.9531.

Yours truly,

MATRIX SOLUTIONS INC.



Natasha Cyples, M.Sc., P.Geo.
Fluvial Geomorphologist

NC/vc
Attachments

Reviewed by



Roger Phillips, Ph.D., P.Geo.
Senior Geomorphologist

September 15, 2022

DISCLAIMER

Matrix Solutions Inc. certifies that this report is accurate and complete and accords with the information available during the project. Information obtained during the project or provided by third parties is believed to be accurate but is not guaranteed. Matrix Solutions Inc. has exercised reasonable skill, care, and diligence in assessing the information obtained during the preparation of this report.

This report was prepared for Morrison Hershfield Ltd. The report may not be relied upon by any other person or entity without the written consent of Matrix Solutions Inc. and of Morrison Hershfield Ltd. Any uses of this report by a third party, or any reliance on decisions made based on it, are the responsibility of that party. Matrix Solutions Inc. is not responsible for damages or injuries incurred by any third party, as a result of decisions made or actions taken based on this report.

VERSION CONTROL

Version	Date	Issue Type	Filename	Description
V1.0	28-June-2022	Final	24316-531 Rockcliffe Geomorph Existing Conditions LR 2022-06-28 final V1.0.docx	Issued to client
V2.0	15-Sep-2022	Final revised	24316-531 Rockcliffe Geomorph Existing Conditions LR 2022-09-15 final V1.0.docx	Reissued to client

REFERENCES

- Chow. 1959. *Manning's n for Channels*. 1959.
[http://www.fsl.orst.edu/geowater/FX3/help/8 Hydraulic Reference/Mannings n Tables.htm](http://www.fsl.orst.edu/geowater/FX3/help/8%20Hydraulic%20Reference/Mannings%20n%20Tables.htm)
- Church M. 2006. "Bed material transport and the morphology of alluvial river channels." *Annual Review of Earth and Planetary Science* 34: 325–354. 2006.
- Galli J. 1996. "Rapid Stream Assessment Technique (RSAT) Field Methods." Draft memorandum. Metropolitan Washington Council of Governments. Washington, DC, USA. 36 pp. 1996.
- Komar P.D. 1987. "Selective grain entrainment by a current from a bed of mixed sizes: A reanalysis." *Journal of Sedimentary Research* 57 (2): 203–211. 1987.
- Miller M.C. et al. 1977. "Threshold of sediment motion under unidirectional currents." *Sedimentology* 24: 507–527. 1977. <https://onlinelibrary.wiley.com/doi/10.1111/j.1365-3091.1977.tb00136.x>
- Ontario Ministry of the Environment (MOE). 2003. *Stormwater Management Planning and Design Manual*. Queen's Printer. Ottawa, Ontario. March 2003. 2003.
<http://www.ontario.ca/document/stormwater-management-planning-and-design-manual>
- Wolman M.G. 1954. "A Method of Sampling Coarse River-Bed Material." *American Geophysical Union* 35 (6): 951–956. December 1954.

Rapid Geomorphic Assessment and Rapid Stream Assessment Technique

RAPID GEOMORPHIC ASSESSMENT (RGA)

Date: Dec 3/20 **Reach:** Lavender Creek **Crew:** NC/AN/RP
Location: Toronto, ON (Rockliffe Ct.)
Weather Description: 1 degree, overcast, cold/darr **Recorder:**

FORM / PROCESS	GEOMORPHIC INDICATOR		PRESENT? (✓)		FACTOR VALUE
	Num	Description	No	Yes	
Evidence of Aggradation (AI)	1	Lobate Bar	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	2	Coarse materials in riffles embedded	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	3	Siltation in pools	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	4	Medial Bars	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	5	Accretion on point bars	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	6	Poor longitudinal sorting of bed materials	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	7	Deposition in the overbank zone	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Sum of Indices:			5	2	0.28571

7

Evidence of Degradation (DI)	1	Exposed bridge footing(s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	2	Exposed sanitary / storm sewer / pipeline / etc.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	3	Elevated sorm sewer oufalls	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	4	Undermined gabion baskets / concrete aprons / etc.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	5	Scour pools d/s of culverts / storm sewer outlets	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	6	Cut face on bar forms	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	7	Head cutting due to knick point migration	<input type="checkbox"/>	<input type="checkbox"/>	
	8	Terrace cut through older bar material	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	9	Suspended armour alyer visible in bank	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	10	Channel worn into undisturbed overburden / bedrock	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Sum of Indices:			7	3	0.3

#

Evidence of Widening (WI)	1	Fallen / leaning trees / fence posts / etc.	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	2	Occurrence of large organic debris	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	3	Exposed tree roots	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	4	Basal scour on inside meander bends	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	5	Basal scour on both sides of channel through riffle	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	6	Gabion baskets / concrete walls / etc. out flanked	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	7	Length of basal scour >50% through subject reach	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	8	Exposed length of previously buried pipe / cable / etc.	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	9	Fracture lines along top of bank	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	10	Exposed building foundation	<input type="checkbox"/>	<input type="checkbox"/>	
Sum of Indices:			2	7	0.77778

9

Evidence of Planimetric Form Adjustment (PI)	1	Formation of chute(s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	2	Single thread channel to multiple channel	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	3	Evolution of pool-riffle form to low bed relief form	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	4	Cut-off channel(s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	5	Formation of island(s)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
	6	Thalweg alignment out of phase meander form	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
	7	Bar forms poorly formed / reworked / removed	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Sum of Indices:			6	1	0.14286

7

COMMENTS: medial bar in one location, not a strong indicator
however provides some evidence of aggradation
localized evidence of sorting across bars
ill-defined pool-riffle sequence, lack of deep pools
channel likely artificially entrenched, banks could be fill, not a natural corridor

STABILITY INDEX: 0.37659

Condition: Transitional

~ Factor Value = # YES / Total #

~ STABILITY INDEX (SI) = (AI+DI+WI+PI)/4

SI ≤ 0.20 = In Regime

SI 0.21 - 0.40 = Transitional or Stressed

SI ≥ 0.41 = In Adjustment

RAPID STREAM ASSESSMENT (RSAT)

Date: Dec 3/20 **Reach:** Lavender Creek **Crew:** NC/AN/RP
Location: Toronto, ON (Rockcliffe Ct.)
Weather Description: 1 degree, overcast, cold/dan **Recorder:** NC

	<i>Excellent</i>	<i>Good</i>	<i>Fair</i>	<i>Poor</i>	<i>Points</i>
Channel Stability	9 - 11	6 - 8	3 - 5	0 - 2	2
Scour / Deposition	7 - 8	5 - 6	3 - 4	0 - 2	4
Instream Habitat	7 - 8	5 - 6	3 - 4	0 - 2	4
Water Quality	7 - 8	5 - 6	3 - 4	0 - 2	2
Riparian Conditions	6 - 7	4 - 5	2 - 3	0 - 2	3
Biological Indicators	7 - 8	5 - 6	3 - 4	0 - 2	4
Total:					19

Stability Rankings: <20 = **LOW** 20 - 35 = **MODERATE** >35 = **HIGH**
 ☒ ☐ ☐

Site Photographs



*Matrix Solutions Inc.
December 3, 2020*

1. Lavender Creek downstream of Symes Road crossing; debris jam immediately downstream of culvert and channel bed is heavily armoured with riprap.



*Matrix Solutions Inc.
December 3, 2020*

2. View downstream of Symes Road; left bank is actively eroding as evidenced by exposed tree roots, leaning trees, bank undercutting, and leaning fence atop the bank.



*Matrix Solutions Inc.
December 3, 2020*

3. View downstream; channel follows a relatively straight planform; most banks are undercut and contain exposed tree roots and leaning trees.



*Matrix Solutions Inc.
December 3, 2020*

4. Elevated storm sewer outfall on left bank; concrete pad along bank at been undermined and is failing.



*Matrix Solutions Inc.
December 3, 2020*

5. View upstream towards bridge crossing; large, well-sorted gravel medial bar with dominant flow path towards left bank.



*Matrix Solutions Inc.
December 3, 2020*

6. View upstream; right bank actively eroding, bank contains exposed parent material.



*Matrix Solutions Inc.
December 3, 2020*

7. View towards downstream extent of Lavender Creek; on inner bank, note exposed parent material at toe of bank and bank slumping.



*Matrix Solutions Inc.
December 3, 2020*

8. Exposed manhole on right bank; bank is near vertical and continues to erode.



*Matrix Solutions Inc.
December 3, 2020*

9. View downstream towards confluence with Black Creek; channel bed and banks become concrete-lined as approaching Black Creek.



*Matrix Solutions Inc.
December 3, 2020*

10. Confluence with Black Creek; note large vertical drop ~1m in height in concrete where Lavender Creek discharges into Black Creek.