German Mills Creek Sanitary Infrastructure Protection Project Site P-057 (YOR-006)

Remedial bank stabilization works at Site P-057 (**Figure 1**) included the installation of a 130-metrelong round stone revetment, two woody debris treatments and three rock vanes to provide protection to the channel bank immediately surrounding the adjacent York Region sanitary line and associated maintenance hole (**Figure 2**). These remedial works were completed in spring 2018.




Figure 1. Site P-057 project location. Source: TRCA, 2018.







Figure 2. Round stone revetment at Site P-057. Source: TRCA, 2018.